



DRILLING AND BORING IN THE LATHE

Figs. 120 & 121—
Wooden-pad
Pilots for Flat
Drill



Figs. 122 & 123—Rose
Reamer and Drill
Reamer

Figs. 124 & 125
—Solid Type of
D-bit

